Release Notes

Floodlight™ MS Healthcare Professional's Portal

Software version: 1.7 | Document version: 10.0

Material Number: 09342346001

© 2023 F. Hoffmann-La Roche Ltd

© F. Hoffmann-La Roche Ltd 2023

All rights are reserved. Reproduction or transmission, in whole or in part, in any form or by any means, electronic, mechanical or otherwise, is prohibited without the prior written consent of the copyright owner.

Copyrights and all other proprietary rights in any software and related documentation ("Software") made available to you rest exclusively with Roche or its Licensors. No title or ownership in the Software is conferred to you. Use of the Software is subject to end user license agreement.

FLOODLIGHT MS is a trademark of Roche.

ANDROID, GOOGLE and GOOGLE PLAY logo are trademarks of Google, LLC. APPLE, APPLE logo and APP STORE are trademarks of Apple Inc. All other product names and trademarks are the property of their respective owners.

Floodlight™ MS Healthcare Professional's Portal might contain components or modules that are Open Source or commercial software programs.

To the maximum extent permitted by law, you shall not decompile and/or reverse engineer the software or any part thereof.

Not for diagnostic, monitoring or therapeutic purposes or in any other manner for regular medical practice.

Roche Molecular Systems, Inc.

2881 Scott Boulevard

Santa Clara, California 95050

United States of America

Made in the USA	
REF	09342346001
Date of Publication	04-04-2023
	floodlightms.com
Please contact Roche to request a printed version of this document.	

Symbols used

The following table displays the symbols used in this Release Notes.

	Product manufacturer: The name and address of the application's manufacturer.
REF	**Reference Number:** Indicates the Reference or Catalog number for this user manual.
	Consult instructions for use: The device includes electronic instructions for use (eIFU).
	Warnings and Precautions: Highlights information that is critical for optimal performance of the system. May also indicate that loss of data or invalid data could occur if the precautions or instructions are not observed.

Preface

The Floodlight™ MS Healthcare Professional's Portal allows you to:

- View data collected by your patients using the Floodlight™ MS Mobile Application between clinic visits
- Review how MS impacts their cognition, hand function, and gait
- Improve the conversation around their care

Intended Use

The Floodlight™ MS Healthcare Professional's Portal is intended to display the results of various assessments from the app per end-user and for several users over time. The HCP is solely responsible for interpreting the results.

What's New?

This release of the Floodlight™ MS Healthcare Professional's Portal has been updated with bug fixes to improve your user experience. Check it out!

This Floodlight™ MS Mobile Application release also includes enhancements to the Floodlight™ MS 2MWT. As a result, your patients may see changes in their step intensity in the new release compared to the previous releases. This may not represent a change in their gait function. Over time, their results will stabilize and thus, become reflective of longer-term trends. If you have questions related to the enhancements in this release, please contact Roche customer support.

Warnings and Precautions

Read the explanation for the data displayed in a patient's chart to understand the meaning of an increase and decrease of a metric value as well as the Y-axis labels. For more information, see the **Review a patient record** section in the Floodlight™ MS Healthcare Professional's Portal user manual.

Refer to the **Supported Platforms** (on page 7) section to ensure that the hardware and software requirements are met.

Supported Platforms

The following table displays the supported platforms for the Floodlight™ MS Healthcare Professional's Portal.

Platforms	Version
DHP: dhp-api-gateway	dev_2168
DHP: dhp-gql-query-svc	dev_1396
DHP: dhp-patient-mgmt-svc	dev_5195
Floodlight™ MS SDK: iOS	1.7
Floodlight™ MS SDK Android	1.7
Floodlight™ MS SDK Backend	1.7

Known Limitations and Workarounds

The following issues are identified as known issues with workarounds in the current release of Floodlight™ MS Healthcare Professional's Portal.

Automatic log-out does not work on some pages

When you first set up your account in the Floodlight™ MS Healthcare Professional's Portal, the automatic log out feature does not work. In this case, click **Log out** on the Navigation Panel at the end of your first session.

Team Owner can invite only registered users to their Team

In the Floodlight™ MS Healthcare Professional's Portal, a Team Owner can invite only a registered user as a Team Member. If you need to add a Team Member who is not already registered, please contact your system administrator or Roche. to first register the user.

QR code image is not displayed in the welcome email sent to an HCP

If the Floodlight™ MS Healthcare Professional's Portal sends a welcome email to an HCP using a Gmail account, the welcome email does not display the QR code image for the HCP. In this case, the HCP can either use the alphanumeric code or use the **Generate My Code** option in the portal to generate the QR code image for enrolling patients.

Known Limitations without present workarounds

The following limitations are unresolved in the current release of Floodlight™ MS Healthcare Professional's Portal. Resolutions or workarounds will be communicated in future release notes.

- The Team Member invitation email is sent in the language set for the sender instead of the language set for the recipient of the email.
- When a Team Owner account is disabled, the patients associated with the HCP still appear in the **All Patients** list and the **Unassigned Patients** list of the other Team Members.
- In some cases, if the patient and the HCP are located in different timezones, the HCP may not be able to see all of the patient data right away.
- For German and Finnish translations, the landing page for the Floodlight™ MS Healthcare Professional's Portal Help Center may show a word cut off on the screen when displayed on a monitor with a low resolution.